


EFFORTLESS
COVERAGE
手順で手軽

IWATA REVOLUTION AIRBRUSH SERIES
M SERIES HP-M1 / HP-M2



EFFORTLESS
COVERAGE
手順で手軽

IWATA REVOLUTION AIRBRUSH SERIES
M SERIES HP-M1 / HP-M2

#	ITEM DESCRIPTION	PRICE CODE	ITEM #	HP-M1	HP-M2
1	Needle Cap	0.3	A 17014	■	x
		0.4	A 17015	x	■
2	Nozzle Cap	0.3	C 17024	■	x
		0.4	C 17025	x	■
4	Nozzle	0.3	E 17044	■	x
		0.4	E 17045	x	■
9	Needle Packing Screw Set(PTFE)	B	17251	■	■
10	Air Valve O-ring	A	11451	■	■
12	Air Valve Set	F	17122	■	■

#	ITEM DESCRIPTION	PRICE CODE	ITEM #	HP-M1	HP-M2
17	Main Lever	C	17143	■	■
23	Needle	0.3	E 17176	■	x
		0.4	E 17177	x	■
24	Needle Chucking nut	A	17153	■	■
28	Lid	C	17183	■	x
		C	17184	x	■
33	Fluid Adjustmet Valve	F	17222	■	■
32	Spanner	A	17651	■	■

■ = yes X = no Opt = optional

Available from: *Dixie Art Airbrush* • www.dixieart.com • 800.783-2612